ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
DASARAHALLI	12	Shettihalli
Street ID	**Street Name**	**Significant Landmark**
W1065	NA	Shettyhalli Surroundings
Segment No.	**Total Length (m)**	
12/S-W1065/S023913	115.14	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	115.14	77.515981	13.064067	77.517042	13.064038	W1045	W1078

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Construction of Toilet to Shettyhalli Anganawadi Building and Other Works in ward no-12 Shettyhalli Sub Division	1000000	2019
Year	**Type of Work**	**Other Work Type**
2019 - 2020	Others	
Tender	**Work Details**	**Job No. / Work Code**
Not a Tender	Construction of Toilet to Shettyhalli Anganawadi Building and Other Works in ward no-12 Shettyhalli Sub Division	012-19-000022
Work Order No.	**Work Order Date**	**Period of Extention**
EE/DD/WO/ /2019-20	01/02/2020	
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
15/06/2020	14/06/2021	Yes

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
KRIDL		0.00
Phone No.	**E-Mail ID**	
9945044476		

Field Inspection Details

Number of Trees	Any Other Information	Name
0		AP Shivakumar
Date of Inspection	**Remarks**	
30/11/2020		

Category	Image	Photo Remark
Road Condition		Location was not determined.
Road Condition		Location was not determined.
Road Condition		Location was not determined.

Remarks

Designation	Approver Name	Date	Target Date	Remark